



ATTENTION: GPS Speedometer Recall - Hot Start resistor fix

For Immediate Release - January 11, 2013 - Speedhut, Inc. of Orem, Utah is issuing the following consumer repair to be performed on all **4" GPS speedometers purchased from October 1, 2012 to January 10, 2013.**

4" GPS speedometers manufactured in the noted date range contain an incorrect electrical component installed on the unit's internal circuit board. The provided resistor module should be placed in-line with the Speedometer's "Hot Start" wire (Red wire with black stripe). **Failure to install this module prior to connecting the "Hot Start" wire to a voltage source will result in permanent damage to the GPS speedometer.**

If you do not feel comfortable performing the resistor module installation please contact us and we will be happy to issue an RMA for your speedometer and repair it in house.

